Type	ļ	#	Hits	Search Text	DBs	Time Stamp Co	Comments	Error Definition	Erro
1	L241		800	USPAI US-PQ B; EI B; EI JPO; ; IBB	SPU SO;	2001/12/20 16:40			0
į.	L2,	L242	2829	kv same metal	D E	2001/12/2016:40			0
1	L2	L243	64	kv near metal	USPAT; US-PGPU B; EPO; JPO; DERWENT ; IBM TDB	2001/12/20 16:43			0
•	1.2	L244	1750	"42" near alloy		2001/12/20 17:34			0
	 L2	L245	610	1244 and ceramic	USPAT; US-PGEU B; EPO; JPO; DERWENT ; IBM	2001/12/20 16:55			0
1		L246	525	L245 and metal	5	2001/12/20 16:58	Y		0
1	12	1247	0	koval near kv	D	2001/12/20 17:31			0
1	77	L248	2829	metal same kv	USPAT; US-PGPU B; EPO; JPO; DERWENT ; IBM	2001/12/20 16:59			

Н	#=	Hits	Search Text	DBs	Time Stamp	Comments	Error Definition	Frro
L249		08	1248 and 257/\$.ccls.	USPAT; US-PGPU B; EPO; JPO; DERWENT ; IBM	2001/12/20 17:13			0
L250		1	("6316826").PN.	1	2001/12/20 17:24			0
L251		23	1244 and kv	D E	2001/12/20 17:25			0
L252		2	kovar near kv	D . F	2001/12/20 17:32			- 0
L254		28836	L and molybdenum	D N H	2001/12/20 17:37			0
L255		99	L253 and molybdenum	D E	2001/12/20 17:39			0
1256	10	35	L253 and (copper with molybdenum)		2001/12/20 17:40			0
1.253		301	("42" near alloy) with Kovar	USPAT; US-PGPU B; EPO; JPO; DERWENT ; IBM	2001/12/20 18:24			0
L257	7	169	253 and ceramic	USPAT; US-PGPU B; EPO; JPO; DERWENT ; IBM TDB	2001/12/20 18:28			0